

To: Way, Steven[way.steven@epa.gov]; Matt Francis[m.francis@erllc.com]
Cc: Bob Heeter[bheeter@harwest.com]; Chris Hassel[CHassel@harwest.com]
From: Christoph Goss
Sent: Wed 9/9/2015 10:04:15 PM
Subject: RE: Gold King Shotcrete

Done

Let me know when the shotcrete operation will begin so that I can be on site.

Christoph

From: Way, Steven [mailto:way.steven@epa.gov]
Sent: Wednesday, September 09, 2015 3:45 PM
To: Matt Francis <m.francis@erllc.com>
Cc: Bob Heeter <bheeter@harwest.com>; Christoph Goss <christoph.goss@deereault.com>; Chris Hassel <CHassel@harwest.com>
Subject: Re: Gold King Shotcrete

As summary, my understanding is the following:

1. HW (Bob) will get the shotcrete mix design to Christoph (Deere and Ault). This mix shall specify whatever HW is recommending, including the accelerant additive if that is in fact what HW recommends for the portal shotcrete.
2. Christoph will then review / approve / comment on the mix design.
3. The shotcrete mix design is to be provided today and execute an order as soon as possible to allow the shotcrete work to proceed. If there is a problem, please inform Matt today.

Thank you,

Steve

Sent from my iPad

On Sep 9, 2015, at 10:28 AM, Matt Francis <m.francis@erllc.com> wrote:

There seems to be some delay in getting the shotcrete spec finalized and approved. EPA/ER being in the middle of these discussions doesn't seem to be the most efficient means of resolving. This needs to be resolved today to match the significant progress being made on site by the work crew. Please communicate directly and respond with the results.

Bob Heeter: Personal Phone/Ex. 6

Christoph Goss: Personal Phone/Ex. 6

Thank You

Matt Francis

Environmental Restoration, LLC

303.994.6611

this

y

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.